

Technical announcement

FinePix S5Pro Firmware (camera control software) Ver.1.08

Wednesday 27th June 2007

Purpose of firmware update:

To resolve a slight issue between the FUJIFILM FinePix S5 Pro and the Nikon MB-D200 Multi-Battery Pack.

Sometimes the FinePix S5 Pro camera may freeze due to contact failure between FinePix S5 Pro and MB-D200.

The firmware update version 1.08 will fix this problem.

Where can I download the update:

<http://www.fujifilm.com/products/digital/download/s5pro/fupd.html>

How can I tell if my camera is already installed with this version of firmware?

This version of firmware has been applied to all new models since June 2007. Cameras produced in June 2007 will have a green round sticker next to the serial number barcode on the original packaging. All cameras produced from July 2007 will have no sticker but the serial numbers will be 73***** or over.

Please note:

Even after applying the firmware update with your S5 Pro, there may be a small possibility that you can still experience the same symptom as above. Please check the following points:

- When attaching the MB-D200 to the S5 Pro, please ensure it is fastened tightly by pressing the lower side of MB-D200 towards the camera.
- Over time, the mounting screw of the MB-200 can become loose. Please fasten the screw tightly again.
- The contact failure can occur due to loose contacts on the MB-D200 itself. If you have installed the firmware update, checked the above and are still experiencing the problem, we recommend you contact Nikon for further assistance.

Should you have any further questions relating to this firmware upgrade, please contact the FUJIFILM UK Product Support Line on **0870 084 1310**